

WALK-A-SURED CLEAR AND ROLL-ON

Information Sheet for Surface Preparation, Mixing, Application and Cleanup of WALK-A-SURED CLEAR and ROLL-ON Safety Floor, Deck & Ramp Resurfacer Kits.

TO THE INSTALLER

*The successful use of this fine product depends upon its proper use!
Please take a few minutes to review the following suggestions. . .*

STORAGE

Store Walk-A-Sured Clear and Roll-On in an area where the temperature is 50°F or above. If Walk-A-Sured Clear and Roll-On has been stored in a cold area, bring its temperature gradually up to 65°F to 80°F before mixing, to insure complete and easier blending. If Walk-A-Sured Clear and Roll-On has been frozen inadvertently, use gentle heat to thaw both the "A" and "B" sides and raise the temperature to 65°F to 80°F before using.

SURFACE PREPARATION

METAL SURFACES: Remove loose rust, scale or corrosion by mechanical scarification, wire brushing, scraping or sandblasting. If the metal surface was greasy or oily, clean it with Methylene Ketone (MEK) or Wooster Floor Prep. Apply the Walk-A-Sured Clear and Roll-On as soon as possible to avoid corrosion. Follow the enclosed Instruction Sheet for the safe and effective use of Wooster Floor Prep.

CONCRETE, TERRAZZO, MARBLE, SLATE, STONE SURFACES: If possible, abrade the surface with sandblasting or mechanical scarification. If the surface was oily, greasy or soiled, clean with Wooster Floor Prep furnished with the kit, following Instruction Sheet carefully regarding safety and use.

NOTE: Walk-A-Sured Clear and Roll-On are not intended for use over glazed tile or quarry tile, unless the tile can first be abraded with aluminum oxide or silicon carbide wheel, or blasted with aluminum oxide or garnet abrasive.

VINYL, EPOXY, URETHANE SURFACES: Remove any loose materials. Rough up glazed surfaces, remove wax with coarse grinding disc. Clean surface with Wooster Floor Prep if the surface was oily, greasy, soiled or waxed, following the enclosed Instruction Sheet.

NEW CONCRETE SURFACES: Etch and neutralize new concrete laitance with Muriatic Acid (15% Hydrochloric Acid solution). Spread at the rate of 1 gallon to every 6 square yards using a stiff bristled broom, until bubbling subsides (usually about 15 minutes). Rinse thoroughly with high pressure hose. Allow surface to dry before applying Walk-A-Sured Clear and Roll-On.

WOOD SURFACES: Walk-A-Sured Clear and Roll-On can be applied directly to new wood surfaces. Walk-A-Sured Clear and Roll-On will also adhere to Wolmanize-treated wood. May not be suitable for wood surfaces where freeze and thaw conditions exist, due to expansion differences.

NOTE: Walk-A-Sured Clear and Roll-On will not adhere to Penta-treated or creosoted wood!

PAINTED, VARNISHED SURFACES: Remove any loose finish. Rough up any glossy surface by sanding or grinding with medium size abrasive. If surface was greasy or oily, clean with Wooster Floor Prep, following use instructions carefully.

SURFACE PREPARATION NOTES:

- ...Always allow wet surfaces to dry thoroughly before applying Walk-A-Sured Clear and Roll-On!
- ...Test the surface for cleanliness before applying Walk-A-Sured Clear or Roll-On. Apply water to the surface to be coated. If the water "beads up," repeat the cleaning process. If the water smooths out and wets easily, the surface is ready to coat.



WOOSTER PRODUCTS INC.
1000 Spruce Street
P.O. Box 6005 • Wooster, Ohio 44691-6005
1-800-321-4936 • 330-264-2844 • Fax 330-262-4151
Web-Site: <http://www.wooster-products.com>
E-mail: Sales@wooster-products.com

BULLETIN No. 710C - 05

PRECAUTIONS: Walk-A-Sured Clear and Roll-On are moderately toxic in uncured state. Prolonged or repeated contact may cause eye irritation and other allergic responses such as skin irritation or dermatitis. Use with adequate ventilation. Avoid breathing of vapor. Avoid skin contact. Wear protective gloves. If skin contact occurs during use, wash immediately with soap and water. Solvents should not be used to wash epoxy off skin as this dilutes the epoxy and tends to carry it into the skin.

IMPORTANT: THIS IS A PRE-WEIGHED, PRE-MEASURED SYSTEM. YOU MUST MIX THE ENTIRE CONTENTS OF PART B WITH PART A. DO NOT TRY TO DIVIDE INTO SMALLER PROPORTIONS.

APPLICATION / MIXING

HOW TO MIX: For easiest mixing, the Walk-A-Sured Clear and Roll-On should be above 50°F. Stir the contents of small can (Part B), then pour the entire contents into large can (Part A). Using a heavy-duty variable speed electric drill with the blending agitator that is included with the Walk-A-Sured Clear and Roll-On kit will enable you to obtain the best mixing results. We do not recommend trying to mix this system manually. Secure the shaft of the agitator in the chuck of the drill, then immerse that agitator into the large can (Part A) until it is submerged about 1/2 in the Walk-A-Sured Clear and Roll-On. Hold the agitator at approximately a 45° angle and start mixing at a slow rate of speed. As the Walk-A-Sured Clear and Roll-On becomes mixed, it will begin to thin out. When this occurs, the speed of the mixer can be increased. Periodically submerge and move mixer around the bottom of the can to pick up any grit that has settled to the bottom. Mix for 5 minutes or until color is uniform, all the grit is in suspension and the epoxy is fluid. When the Walk-A-Sured Clear and Roll-On is completely mixed, it will be of a consistency similar to a thick paint.

NEAT EDGE: If a neat edge is desired, mask off area to be covered with duct tape. As soon as application of epoxy has been completed, remove the tape. Be sure that the tape does not drag across Walk-A-Sured Clear and Roll-On while removing.

WORK LIFE: Approximately 30 to 60 minutes after emptied from the can. Work life is longer at cooler temperatures — shorter at warmer temperatures.

SURFACE TEMPERATURE: Be sure that the surface to be coated is above 50°F before applying Walk-A-Sured Clear and Roll-On.

APPLICATION: Apply Walk-A-Sured Clear and Roll-On with 1/4" epoxy paint roller.

CLEAN UP

Tools may be cleansed with xylene or methyl ethyl ketone (MEK). Clean up should be done before material cures. Cured or hardened epoxy is almost impossible to remove.

PRECAUTIONS

Epoxy resins and their hardeners may cause dermatitis in susceptible individuals. Keep epoxy Walk-A-Sured Clear and Roll-On off skin and out of eyes. In case of accidental skin contact, wash thoroughly with soap and water. In case of eye contact, flush out with warm water and consult a physician immediately. Use only in well ventilated areas. Wear protective clothing and solvent resistant protective gloves while using.

IMPORTANT NOTICE TO PURCHASER: THE FOLLOWING IS MADE IN LIEU OF ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE: Purchase or use of this product constitutes an agreement with Seller and Manufacturer that, if the product proves to be defective or in any way unsuitable, Seller's and Manufacturer's limit of liability for all damages, including but not limited to incidental or consequential damages, and User's or Purchaser's exclusive remedy, regardless of legal theory, including theories of breach of warranty, negligence and strict liability, shall be to receive at Seller's or Manufacturer's option, repair of the defective product, an equivalent quantity of replacement product or a refund of the purchase price.